



Wire 1 + 2	Heating element
Wire 3 + 4	Temperature sensor
Wire 5+6	Moist sensor
	5=Center ring
	6=Middler ring

300 Ohms +/-10%
 12 kOhms @ 25°C / 77°F
 38 kOhms @ 0°C / 32°F
 Dry = infinite resistance
 Wet = <100.000 Ohms

* Ver. 2 : special label